




Dissecting the Failure of a Newly Constructed Dam

Rodney E. Holderbaum, PE



Hope Mills Dam – Prior to 2010 Failure







Hope Mills Dam – Hope Mills, NC

HISTORY:

- 1839: Rock-Filled Timber Crib Dam; Failed in 1923 during a flood; Life span = 84 years
- 1924: Embankment Dam; Failed in 2003 during a flood; Life span = 79 years
- 2007-2008: Concrete, Pile-Supported Dam; Failed in 2010 (sunny-day failure); Life span = 2 years
- Oct 2012: Lawsuit filed by Town
- July 2014: Legal settlements reached























































Hope Mills Dam

Post-Construction Monitoring

- Visual inspections (quarterly)
- Survey monitoring
 - Structural movement
- Drain pressure measurements
 - Pressure gages added during construction
- Drain flow observations
 - Visual only, no measurements




Hope Mills Dam – Drain Flow-September 2009





Hope Mills Dam - Drain Flow-December 2009

























Hope Mills Dam – Cause of Failure

Conditions Required for Piping:

- Seepage
- Erodible Soil
- Sufficient Hydraulic Gradient
- Unfiltered Outlet



Hope Mills Dam – Cause of Failure

Factors Likely Contributing to Failure:

- Location of foundation cutoff wall
 - Resulted in structure uplift
 - Caused high flow gradient to develop
- Pile foundation
 - Low confining stresses in foundation soils
- Use of geotextile as a filter
 - Numerous locations for filter discontinuity
- Presence of sheet pile overlap
 - Created a potential seepage path
- Failure to recognize clear warning signs during monitoring program









Dissecting the Failure of a Newly Constructed Dam

Rodney E. Holderbaum, PE

