

Tale of Three Projects

Addressing Dam Safety Concerns within the Muskingum River Basin, OH

**AEG Annual Meeting
September 2015**

**Mike Nield, Geologist
U.S. Army Corps of Engineers
LRH Dam Safety Production Center**

**Coauthors:
Adam Kays, Geotechnical Engineer
Seth Lyle, Geotechnical Engineer
Jeff Maynard, Structural Engineer**



® For Official Use Only (FOUO)



TALE OF THREE PROJECTS - OUTLINE


A. MUSKINGUM REGION

- 1. Project Locations**
- 2. Project Descriptions**
- 3. Local Geology**

B. DOVER DAM (foundation anchors)

C. BOLIVAR DAM (seepage barrier & grouting)

D. ZOAR LEVEE (risk assessment)



MUSKINGUM WATERSHED



- ◆ Located in eastern Ohio, within Muskingum River Watershed
- ◆ System of 16 USACE dams, mostly built in 1930's, within Muskingum River Watershed for flood control, recreation and water quality
- ◆ Dam/Levee Reevaluation
 - Changing Criteria
 - Poor Performance During High-Water Events
 - Portfolio of Dams Prioritization based on Risk Assessments




BUILDING STRONG®


PROJECT LOCATIONS

Three Projects

1. Dover Dam: Concrete gravity dam, founded on bedrock, run-of-river
2. Bolivar Dam: Earthen dam, founded mostly on glacial outwash, run-of-river
3. Zoar Levee: Earthen levee, founded mostly on glacial outwash, located within Dover pool.



GEOLOGY




- Near-horizontal sedimentary rock (bedding)
- Pennsylvanian aged Pottsville Group
- Interbedded sandstone, shale, siltstone, claystone with thin seams of coal and limestone
- Typically joints are high angled with smooth and planar surfaces.
- Solutioned discontinuities are common in thin limestone units.



BUILDING STRONG®

GLACIAL GEOLOGY




- Unglaciaded
- Located near the ice margins of Illinoian and Wisconsin glacial periods
- Site geology Influenced by glacial lakes and outwash.
- Typically, +100' proglacial soil deposits within valley bottom.



BUILDING STRONG®

LOCAL GLACIAL GEOLOGY



Wisconsin Ice Margin

BOLIVAR DAM

Illinoian Ice Margin

ZOAR LEVEE


DOVER DAM

WISCONSINAN (14,000 to 24,000 years old)	ILLINOIAN (130,000 to 300,000 years old)	PRE-ILLINOIAN (older than 300,000 years)	Kames and eskers
Ground moraine	Ground moraine	Ground moraine	Outwash
Wave-planed ground moraine	Dissected ground moraine	Dissected ground moraine	Lake deposits
Ridge moraine	Hummocky moraine		Peat
			Colluvium




BUILDING STRONG®


PRE GLACIAL DRAINAGE




ILLINOIAN ICE ADVANCE




WISCONSIN STAGE ICE ADVANCE




WISCONSIN STAGE – GLACIAL LAKE




WISCONSIN ICE ADVANCE – GLACIAL LAKE




WISCONSIN ICE ADVANCE – LAKE DRAINS



WISCONSIN ICE ADVANCE – GLACIAL OUTWASH



CURRENT DRAINAGE CONDITION



The background of the slide is a grayscale photograph of a large concrete dam with multiple spillways, situated in a river valley. The dam is the central focus of the image, with water visible on either side. The surrounding landscape includes some vegetation and a road in the foreground.

TALE OF THREE PROJECTS - OUTLINE

A. MUSKINGUM REGION

- 1. Project Locations**
- 2. Project Descriptions**
- 3. Local Geology**

B. Dover Dam (foundation anchors)

- 1. Potential Bedrock Sliding Failure**
- 2. Rock Anchor Design**
- 3. Rock Anchor Installation**

C. Bolivar Dam (seepage barrier & grouting)


D. Zoar Levee (risk assessment)

DOVER DAM

Tuscarawas River

- CONSTRUCTION COMPLETED - 1938
- CONCRETE GRAVITY DAM
- FOUNDED ON BEDROCK

DOVER DAM



- 23 MONOLITHS
- 824 FOOT LENGTH
- 338' SPILLWAY LENGTH

DOVER DAM


Spillway 916.0

Non-Overflow 931

71'

Stream Bed 860

- 71' HEIGHT FROM STREAM BED
- "RUN OF RIVER"




DOVER DAM – POOL OF RECORD, Jan 2005

Probable Maximum Flood el. 937

Pool el. 907.4

- Prior to spillway flow, the dam fails to provide protection against sliding
- PMF overtops dam creating downstream erosion and removal of passive wedge
- Dam Safety Action Classification II (urgent)

GEOLOGIC PROFILE



1. Upper Silty Shale
2. Upper Sandstone
3. Shale
4. Upper Mercer Limestone
5. Bedford Coal
6. Lower Silty Shale

7. Lower Mercer Limestone
8. Carbonaceous Shale
9. Middle Mercer Coal/CLS
10. Interbedded Siltstone and Shale
11. Middle Sandstone
12. Interbedded Shales
13. Lower Sandstone



BUILDING STRONG®

BEDROCK UNITS

TOP OF
DAM

900

850

BASE
OF KEY

800

750

GEOLOGIC COLUMN


Unit #8 Carbonaceous Shale

- 3'-6' thick
- Dark gray, soft to mod. hard, carbonaceous

Unit #9 Middle Mercer Coal/Claystone

- <1' thick
- Black, blocky, occ. shaly


Potential sliding failure plane under valley monoliths



BUILDING STRONG®


POTENTIAL SLIDING FAILURE PLANES

TYPICAL VALLEY MONOLITH SLIDING ALONG COAL/CLAYSTONE



POTENTIAL SLIDING FAILURE PLANES


TYPICAL VALLEY MONOLITH SLIDING AT BASE OF CONCRETE CUT-OFF



BUILDING STRONG®

POTENTIAL SLIDING FAILURE PLANES

VALLEY MONOLITHS 12 & 13 SLIDING ALONG THRUST FAULT



BUILDING STRONG®





PLAN VIEW

- 117 Anchors Original Design
- 20 Anchors Added During Construction
- 137 Total Anchors Installed


The plan view shows the dam structure with various basins and aprons. Key features include:

- Basins and Aprons:** North Stilling Basin Apron, Center Stilling Basin Apron, South Stilling Basin Apron.
- Anchors:** Indicated by red pentagons (9 total), yellow triangles (117 original design), and blue circles (20 added during construction).
- Structures:** Retaining Wall, Concrete Baffle (Typ.), Entrance House, Operating House, Rock Fill, Marsh Area, Gravel Surface, Concrete Gutter, End of Stilling Basin, Retaining Wall, R/W Prop.
- Dimensions:** +853.3' (6), +858.3' (11), +859.3' (14).
- Flow Direction:** Indicated by an arrow pointing upstream.

Symbol	# of Anchors	Anchor Size	Anchor Length
	9	54 Strands	124' – 167'

	29	48 Strands	120' – 163'
	14	37 Strands	119' – 138'
	5	19 Strands	103' – 110'
	60	2.5" Bars	63' – 108'

ANCHOR LENGTH GEOLOGIC CROSS SECTION




Monolith M-9



BUILDING STRONG®

ANCHOR LENGTH GEOLOGIC CROSS SECTION




Monolith M-9



BUILDING STRONG®

ANCHOR LENGTH GEOLOGIC CROSS SECTION




Monolith M-9





BUILDING STRONG®

ANCHOR EMBEDMENT DEPTH




CONSTRUCTION

- Phase I was awarded to Brayman Construction Corp in Sep 2010
- Phase II was awarded to Brayman Construction Corp in Sep 2011
- Phase I completed in Aug 2013
- Phase II nearly all work was completed in Dec 2014
- Construction Cost (Phases I & II): approx. \$40 million
- Total Number of Anchors: 137




BUILDING STRONG®

ANCHOR INSTALLATION – ACCESS (Dam)



ANCHOR INSTALLATION – ACCESS (Stilling Basin)

- Contract included in-the-wet construction and bar anchors.
- Contractor proposed dewatering and strand anchors.



COFFER BOX



DEWATERED STILLING BASIN




ANCHOR INSTALLATION - DRILLING

- Hole Depth: 72' – 172'
- Hole Diameter: 6" – 19"
- Down Hole Hammer
- Pilot hole drilled then followed by larger diameter bits.




ANCHOR INSTALLATION – HOLE ALIGNMENT

- Drill Tolerance 1:30 – 1:75
- Directional drilling methods used on select holes. Optical readings on pilot hole.
- Maxibor or Bortrak instruments used for alignment check on final hole.




ANCHOR INSTALLATION - WATERTIGHTNESS

- Hydraulic Pressure Tested
- Tremie and Pressure Grouted.
- Minimize excessive grout penetration.
- Many holes required repeated cycles of redrilling, pressure testing and regrouting.



ANCHOR INSTALLATION – ENCAPSULATION



- Double corrosion protection
- Corrugated Tubing: 100 mil thick if $\geq 10''$, 60 mil for smaller tubing.
- Water Tested: <2.75 gal in 10 min.
- Grout annulus between corrugated tubing and drilled hole in multiple lifts.


Corrugation

Grout Annulus


ANCHOR DETAIL



ANCHOR INSTALLATION – INSTALL STRANDS





- Number of Strands: 5 - 54
- Inspect and repair smooth polyethylene extruded strands.
- Greased and extruded strands in stressing length.
- Bare strands in bond length.
- First Stage Grouted





ANCHOR INSTALLATION – STRESSING

Wedge Plate & Bearing Plate


- Design Load: 60% of MUTS
- Test Load: 133% of Design Load
- Lockoff Load: 70% of Design Load
- Proof , Performance and Creep Tests in accordance with PTI.
- Second stage grouted.



Second Stage Grouting




ANCHOR DETAIL




ANCHOR INSTALLATION – COMPLETION

Cap & Concrete



- Anchor capped and filled with corrosion inhibiting compound.
- Concrete filled recess designed to match the appearance of the dam surface.



ANCHOR DETAIL

OTHER ASPECTS OF DOVER PROJECT



DRILLED SHAFT FOUNDATION



PARAPET WALL



STONE SLOPE PROTECTION



**BEDROCK TIE-IN
GATE STRUCTURE**



BUILDING STRONG®


CHALLENGES DURING CONSTRUCTION

- **Multiple cycles of redrilling, pressure testing and regrouting anchor hole.**
 - *Utilized different grout mixes, varied grouting pressures (safely), isolated zones of high grout takes with packers.*
- **Some anchors slightly exceeded deformation tolerance during creep tests.**
 - *Extended creep test from 10 min to 60 min (PTI), additional liftoff tests at extended times (24 hrs, 48 hrs, 1 week), account for steel elongation based on elastic modulus of steel.*
- **Two anchors (48 & 37 strand), during lockoff/liftoff procedures, had several wedges that failed to properly engage, resulting in broken individual wires and complete 7-wire strand failure.**
 - *Both anchors were replaced and an investigation was completed. Possible cause: wedge geometry, cleanliness of pockets, rust on teeth*
- **Stilling basin slab concrete was thinner than original drawings.**
 - *Increased number of smaller anchors (5 strand) used to better distribute load.*




Dover Dam

- Construction completed, ribbon cutting ceremony this past spring
- Post Implementation Evaluation is ongoing to assess the reduced risks resulting from dam safety modifications.



Sliding concern

Dover Dam is built on a weak foundation of limestone and shale containing fault damage. The force of high water level may cause a section of the spillway to fail, letting it slide along the riverbed.



From Canton, OH newspaper
"The Repository"

TALE OF THREE PROJECTS - OUTLINE

A. MUSKINGUM REGION

B. DOVER DAM (foundation anchors)

- 1. Potential Bedrock Sliding Failure**
- 2. Rock Anchor Design**
- 3. Rock Anchor Installation**

C. BOLIVAR DAM (seepage barrier & grouting)

- 1. Seepage Through Soil Foundation**
- 2. Seepage Wall Construction**
- 3. Bedrock Abutment Seepage**
- 4. Grout Curtain Construction**

D. Zoar Levee (risk assessment)

BOLIVAR DAM

- Earthen Dam Founded on Glacial Outwash
- Built in 1938
- 6,400' Dam Length
- 87' Dam Height (main)
- "Run of River"

Dam Right Abutment)

Dam (terrace embankment)

Tailwater El. 906
(backup from Dover Dam Pool)

Top of Dam wall
Elev. 985.5 feet

Dam (main embankment)

Dam Left Abutment


Pool of Record – El. 951.6
30 year event

Spillway Crest
Elev. 962 feet

Intake Structure

POOL OF RECORD – JAN 2005


SEEPAGE DURING FLOOD EVENTS




SEEPAGE DURING FLOOD EVENTS




DAM FOUNDATION - PROFILE



DAM FOUNDATION CHARACTERISTICS




SEEPAGE REMEDIATION MEASURES



SEEPAGE ANALYSIS – W/O SEEPAGE BARRIER

Bolivar Dam: Pre vs. Post Project Comparison

Pre Seepage Remediation




Pre Seepage Remediation: There is a direct path of seepage from Sandy Creek into the pervious foundation of the dam. The 1980's relief wells and blanket are somewhat effective in reducing head, extending the seepage path, and providing resistance to uplift but are not effective at all pool and tailwater conditions and locations below the dam.

SEEPAGE ANALYSIS – WITH SEEPAGE BARRIER


Post Seepage Remediation

(seepage barrier & filter blanket augmentation complete)



Post Seepage Remediation: Seepage exit gradients are greatly reduced downstream of the dam and the potential piping pathway is cut off reducing the risk of failure of the project to an acceptable level.

SEEPAGE BARRIER & GROUT CURTAIN



BARRIER DIMENSIONS

- * 4,519 FEET LONG
- * UP TO 144 FEET DEEP
- * 2 FEET MIN. THICK


**SEEPAGE
BARRIER**

**GROUT
CURTAIN**

DRILLING AND GROUTING

- * 400 FEET LONG GROUT CURTAIN
- * AVG DEPTH 65 FEET


SEEPAGE BARRIER - CROSS SECTION



BUILDING STRONG®

CONSTRUCTION


- Performance based specs. Procured based on best value procedures. Firm fixed price contract.
- Contract awarded to Treviicos
- Panel method using hydromill with low strength concrete backfill
- Foundation drilling and grouting subcontracted to TerraFirm
- Construction Award Cost: \$44 million
- Notice to Proceed Date: May 2014
- Scheduled Completion Date: Feb 2017



BUILDING STRONG®

BARRIER WALL CONSTRUCTION - GUIDE WALL

- Prepare temporary work surface
- Install concrete guide walls
- Survey panel locations



SEEPAGE BARRIER – CONCEPTUAL PROFILE ALONG CENTERLINE
(looking upstream - not to scale)

PANEL EXCAVATION - CLAMSHELL



TOP OF BARRIER 959 (varies)

- 3' Wide Panels (2' min. specified)
- Initiate panel excavation with clamshell.
- Maintain bentonite slurry level during excavation.

← Bentonite Slurry



**BENTONITE MIXING
DE-SANDING PLANT**




CLAMSHELL

PRIMARY PANEL EXCAVATION - HYDROMILL

- 144' depth (varies)
- 3 & 5 bite primary panels
- Overlapping excavation to assure no gaps between bites



TOP OF BARRIER 959 (varies)



PLAN VIEW – PRIMARY PANEL

144' (varies)

BITE 1

BITE 3

BITE 2

BOTTOM OF BARRIER 815



CUTTER HEAD




HYDROMILL

SURVEY PANEL ALIGNMENT

- Koden used to measure verticality and panel thickness
- Multiple measurements determine barrier wall alignment

TOP OF BARRIER 959 (varies)




PANEL BACKFILL

- Continuous and homogenous
- Minimum UCS 750 psi at 28 days (based on 10 point moving average with no test below 500 psi)
- Plastic, high slump concrete mix (not specified)



Tremie Placement




PRIMARY PANEL

PRIMARY PANEL EXCAVATION



- Drill Mate System measures verticality.
- Adjustments can be made with the hydromill during excavation.




DRILL MATE SYSTEM

PRIMARY PANEL


PRIMARY PANEL

PRIMARY PANEL BACKFILL



SECONDARY PANEL EXCAVATION & CLEANING


- Kodan measurements taken
- Clean sidewalls of bentonite buildup
- Replace bentonite slurry prior to backfill




**PLAN VIEW
PRIMARY & SECONDARY PANELS**



CLEANING PANEL SIDEWALLS



SECONDARY PANEL BACKFILL




DEMONSTRATION SECTION


- Verification Drilling with down-hole-camera.
- In-place permeability $\leq 1 \times 10^{-6}$ cm/s at 28 days.



SEEPAGE BARRIER WALL COMPLETION



GROUT CURTAIN - LOCATION



LEFT ABUTMENT



BUILDING STRONG®

LEFT ABUTMENT – BEDROCK SEEPAGE



2005 FLOOD EVENT



1991 FLOOD EVENT


LOCATION ABOVE STILLING BASIN



BUILDING STRONG®

LEFT ABUTMENT – GEOLOGY

- Soil: (colluvium – fines w/ rock frag.) 16' thick
- Bedrock: Near horizontal, interbedded, sedimentary bedrock
- Two thin (3'-5' thick) limestone units (Upper and Lower Mercer Limestone)




Profile Along Grout Curtain Centerline – Looking Upstream

UPPER AND LOWER MERCER LIMESTONE

- Limestone Units: thin (3' to 5' thick), regionally continuous, very hard, high UCS (as high as 32,000 psi).
- Joints: high angle, solutioned, approx. 5' spacing, joint set at 90°, interconnected, avenues for groundwater flow.
- Bedding planes: low angle, open, solutioned and continuous.
- Exposed in stilling basin and spillway.




OPEN FRACTURES AT SURFACE



**DOWN-THE-HOLE
CAMERA IMAGES**


GROUT CURTAIN – GENERAL INFORMATION

- Double line grout curtain, 10' spacing between grout lines.
- Grout curtain is approx. 400' long, 65' deep with 3" dia. holes
- 20' Spacing between Primary holes
- All Primary and Secondary holes will be drilled and pressure tested. Higher order grout holes will be split spaced, if needed.




GROUT CURTAIN – GENERAL INFORMATION

- Double line grout curtain, 10' spacing between grout lines.
- Grout curtain is approx. 400' long, 65' deep with 3" dia. holes
- 20' Spacing between Primary holes
- All Primary and Secondary holes will be drilled and pressure tested. Higher order grout holes will be split spaced, if needed.
- Downstream grout line hole are mostly inclined 30° toward the spillway



GROUT CURTAIN – GENERAL INFORMATION

- Double line grout curtain, 10' spacing between grout lines.
- Grout curtain is approx. 400' long, 65' deep with 3" dia. holes
- 20' Spacing between Primary holes
- All Primary and Secondary holes will be drilled and pressure tested. Higher order grout holes will be split spaced, if needed.
- Downstream grout line hole are mostly inclined 30° toward the spillway
- Upstream grout line holes are mostly inclined 30° toward the dam/valley




DRILLING THROUGH SOIL & INSTALL CASING

- Hole location and drill mast orientation is surveyed
- Auger drilling method
- Install temporary casing through soil without use of drilling fluids.
- Place grout seal and grout annulus



TYPICAL GROUT HOLE




DRILLING THROUGH BEDROCK

- Drill 3" diameter hole
- Bottom of grout curtain at elev. 924
- Maximum drill length of 115'
- Vertical to 70° from vertical
- Water actuated down-hole hammer
- Hole sidewalls are cleaned
- Bottom of hole deviation magnitude and orientation is measured



TYPICAL GROUT HOLE




PRESSURE TESTING

- Two Zones to treat upper and lower limestone units separately
- Upstage grouting
- Set packer at top of zone
- Pressure is limited during pressure testing and grouting to prevent hydraulic Jacking




PRESSURE TESTING & GROUT CART

TYPICAL GROUT HOLE



GROUTING

- Six balanced stabilized grout mixes
- Computer monitored grouting and pressure testing
- Typically start with thinner mixes and incrementally increase viscosity
- Upstage grouting
- Grouting refusal set at 0.5 gal/min




GROUT MONITORING



GROUT PLANT


TYPICAL GROUT HOLE




DOWNSTAGE GROUTING

- Downstage grouting if significant drill water loss is encountered (+50%), indicating open foundation conditions.
- Stage is pressure tested and grouted prior to deepening the hole.

TYPICAL GROUT HOLE




GROUT RECORDS – UPSTREAM LINE



GROUT PROFILE
(looking downstream)

GROUT TAKES – UPSTREAM LINE



BOLIVAR DAM: SEEPAGE BARRIER & GROUTING



- ONGOING INDEPENDENT EXTERNAL PEER REVIEW
- UPON COMPLETION: POST IMPLEMENTATION EVALUATION

**SEEPAGE BARRIER
APPROX. 20% COMPLETE**



**GROUT CURTAIN
APPROX. 30% COMPLETE**

TALE OF THREE PROJECTS - OUTLINE

A. MUSKINGUM REGION

Zoar, OH

B. DOVER DAM (foundation anchors)


C. BOLIVAR DAM (seepage barrier & grouting)

- 1. Internal Erosion in Soil Foundation**
- 2. Seepage Wall Construction**
- 3. Bedrock Abutment Seepage**
- 4. Grout Curtain Construction**

D. ZOAR LEVEE (risk assessment)


- 1. Diversion Dam**
- 2. Rock Knoll - Levee**
- 3. Ball Field - Levee**

ZOAR LEVEE



- Historic Village (est 1817, German separatist, communal lifestyle)
- Located within Dover Pool
- Earthen Embankment Founded Primarily on Glacial Outwash
- Built in 1938
- Levee Raised 9.5' in 1951
- Poor Performance During Flood Events – DSAC I (after 2008 event)


ZOAR LEVEE – THREE AREAS OF CONCERN



1. Diversion Dam
2. Rock Knoll Reach (Levee)
3. Ball Field Reach (Levee)

Several additional areas of concern are not addressed in this presentation


ZOAR DIVERSION DAM – AERIAL VIEW




ZOAR DIVERSION DAM – GEOLOGIC PROFILE

LOWER MERCER LIMESTONE

- Thin, typically 3 to 4 foot thick
- Solutioned high angled joints and low angled bedding planes create avenues for groundwater seepage
- Limestone is missing in portions of dam footprint




ZOAR DIVERSION DAM – RISK ASSESSMENT



Downstream


Seepage exit
300' d/s

Hypothetical Ground
Water Flow Path
Through Interconnected
Network of Open Joints




Upstream – lake drained

ZOAR LEVEE – THREE AREAS OF CONCERN






1. Diversion Dam
2. Rock Knoll Reach (Levee)

ROCK KNOLL REACH – ZOAR LEVEE



AERIAL VIEW

- Levee Embankment Founded on Glacial Outwash (sands & gravel) and Glacial Lake Deposits (clays & silts)
- Top of Rock 5'- 25' Below Levee Foundation.
- 5' - 20' Levee Height
- Approx 500' Length (sta 30+00 – 35+00)




CROSS SECTIONS




BUILDING STRONG®

ROCK KNOLL REACH - SEEPAGE




BUILDING STRONG®


ROCK KNOLL REACH – GEOLOGIC PROFILE




ROCK KNOLL REACH – FAILURE MODE




ROCK KNOLL REACH – RISK ASSESSMENT



PLAN VIEW



CROSS SECTION




RISK ASSESSMENT (fn chart)



BUILDING STRONG®

ZOAR LEVEE – THREE AREAS OF CONCERN




1. Diversion Dam
2. Rock Knoll Reach (Levee)
3. Ball Field Reach (Levee)

BALL FIELD REACH – ZOAR LEVEE



- Levee Embankment Founded on Glacial Outwash (sands & gravel)
- 38' Levee Height (varies)
- Approx 2,500' Length (ball field reach of levee)



CROSS SECTION



BUILDING STRONG®

BALL FIELD REACH - SEEPAGE



2005




2008



Seepage within Ball Field Reach of Levee

ZOAR LEVEE – GEOLOGIC PROFILE




- LEVEE:** Original levee constructed in 1937 with crest raised in 1951 to elevation 928.5.
- ALLUVIAL BLANKET:** Fine grained clays and silt, recent
- GLACIAL OUTWASH:** Sands and gravels, glacial outwash, Wisconsin ice advance
- GLACIAL LAKE - CLAYS AND SILTS:** Clays and silts, glacial lake deposits, partially eroded and replaced by overlying Upper Glacial Outwash, Wisconsin ice advance
- LOWER ALLUVIUM:** Sand and silty sand with lenses of clays and silts, alluvial and possible isolated glacial lake deposits.
- BEDROCK:** Relatively flat lying sedimentary rock of the Pennsylvanian-aged Pottsville Group




BUILDING STRONG®


ZOAR – STORM DRAIN TRENCH




ZOAR – BIMELER HOUSE FOUNDATION




BALL FIELD REACH – RISK ASSESSMENT



CROSS SECTION



EXISTING REMEDIAL MEASURES




RISK ASSESSMENT (fn chart)



BUILDING STRONG®

BALL FIELD REACH TENTATIVE SELECTED ALTERNATIVE




Internal Erosion Interception Trench (IEIT)




BUILDING STRONG®

BACKWARD EROSION PIPING - FOUNDATION



BUILDING STRONG®

INTERNAL EROSION INTERCEPTION TRENCH (IEIT)



OUTWASH
(sands & gravel)

**INTERNAL EROSION
INTERCEPTION TRENCH**



BUILDING STRONG®

Tale of Three Projects

Addressing Dam Safety Concerns within the Muskingum River Basin, OH

QUESTIONS ?



**US Army Corps
of Engineers**
Dam Safety Modification
Mandatory Center
of Expertise

502 Eighth Street
Huntington, WV 25701

michael.c.nield@usace.army.mil

Michael C. Nield, P.G.
Senior Engineering Geologist
LRD Dam Safety Production Center


Office - (304) 399-5056
Fax - (304) 399-5786

Coauthors:

Adam Kays, Geotechnical Engineer, USACE, Huntington WV
Seth Lyle, Geotechnical Engineer, USACE, Huntington WV
Jeff Maynard, Structural Engineer, USACE, Huntington WV


Marietta OH
1913 Flood

GROUT RECORDS – UPSTREAM LINE



TERRA FIRM
CONSTRUCTION, LLC
1004 N. 1st Avenue, Kansas City, Missouri 64111

SCALE
INTS



R2	ADDED 9 HOLES	5-28-15	KIK
R1	UPDATED FAN HOLE SPACING	5-28-15	KIK
#	DESCRIPTION	DATE	INT
REVISION SCHEDULE			